




# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 60in deck - Model 74991  
60in Side Discharge Deck



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 60in deck - Model 74991  
60in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
<b>Belts</b>						
20	<b>R114-5858</b>	114-5858	Belt - V - Deck	1	<b>120.65</b>	
<b>Rotary Blades</b>						
30	<b>R105-7716-03</b>	105-7716-03	Mower Blade - 20.5 in Lo-Flow	3	<b>16.55</b>	
30	<b>R108-1128</b>	108-1128	Mower Blade Kit - 20.5 in Lo-Flow Set/6	1	<b>0.00</b>	
30	<b>R105-7715-03</b>	105-1115-03, 105-7715-03	Mower Blade - 20.5 in Mid-Flow	3	<b>16.55</b>	
30	<b>R108-1123</b>	108-1123	Mower Blade Kit - 20.5 in Mid-Flow Set/6	1	<b>0.00</b>	
30	<b>R105-7718-03</b>	105-7718-03	Mower Blade - 20.5 in High-Flow	3	<b>16.55</b>	
30	<b>R108-1114</b>	108-1114	Mower Blade Kit - 20.5 in High-Flow Set/6	1	<b>0.00</b>	
30	<b>R105-8777-03</b>	105-8777-03	Mower Blade - 20.5 in Mulcher	3	<b>18.75</b>	
30	<b>R108-1115</b>	108-1115	Mower Blade Kit - 20.5 in Mulcher Set/6	1	<b>0.00</b>	
30	<b>R105-7777-03</b>	105-7777-03	Mower Blade - 20.5 in Recycler	3	<b>16.50</b>	
30	<b>R110-0405</b>	110-0405	Mower Blade Kit - 20.5 in Recycler Set/6	1	<b>0.00</b>	
<b>Wheels</b>						
40	<b>R68-2730</b>	1-603299, 68-2730	Wheel - Anti Scalp	4	<b>7.85</b>	
41	<b>R127-9528</b>	127-9528	Tire & Wheel - 13x6:50-6 Smooth Semi Pneumatic	2	<b>195.25</b>	
<b>Other Parts Available</b>						
70	<b>R106-3253-01</b>	106-3253-01	Plate-Hinge, Front	1	<b>22.95</b>	
<i>Tech Note: (2012-2019)-312000001-403319953:</i>						
71	<b>R108-4059-01</b>	108-4059-01	Plate-Hinge, Rear	1	<b>22.95</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 60in deck - Model 74991  
60in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
<i>Tech Note: (2012-2019)-312000001-403319953:</i>						
72	<b>R106-3246-01</b>	106-3246-01	Deflector	1	<b>37.35</b>	
<i>Tech Note: (2012-2019)-312000001-403319953:</i>						
73	<b>R151416</b>	108-5029, 110-0759, 151416	Deflector - Long	1	<b>37.35</b>	
74	<b>R106-3248-03</b>	106-3248-03	Strap - Discharge	1	<b>14.20</b>	
75	<b>R3231-4</b>	01-157-0440, 01-173-0612, 3231-4	Bolt - Carriage 3/8-16 x 1-1/2	4	<b>1.20</b>	
<i>Tech Note: (2012-2019)-312000001-403319953:</i>						
76	<b>R108-2792</b>	108-2792	Rubber Deflector Assy	1	<b>97.35</b>	
<i>Tech Note: (2012-2019)-312000001-403319953:</i>						
77	<b>R3296-47</b>	3296-47	Locknut - 5/16-18 Jam Nyloc	1	<b>0.59</b>	
78	<b>R108-4052</b>	108-4052	Spring - Torsion	1	<b>14.60</b>	
79	<b>R322-50</b>	322-50	Bolt - Hx HD 5/16-18 x 7 1/2	1	<b>3.75</b>	
80	<b>R109-8590</b>	109-8590	Pulley - Idler	1	<b>112.95</b>	
81	<b>R98-5967</b>	98-5967	Spacer-Wheel	1	<b>10.35</b>	
82	<b>R108-5388</b>	108-5388	Bolt - Hx HD 3/8-16 x 7 1/2	1	<b>9.25</b>	
83	<b>R115-7465-01</b>	115-7465-01	Baffle Assy	1	<b>95.55</b>	
84	<b>R3231-27</b>	3231-27	Bolt - Carriage 3/8-16 x 7/8	8	<b>0.53</b>	
85	<b>R114-5842-01</b>	114-5842-01	Baffle	1	<b>123.15</b>	
86	<b>R98-7913</b>	98-7913	Spacer - Tube	2	<b>5.80</b>	
87	<b>R98-7912</b>	98-7912	Bushing - Spanner Wheel	2	<b>5.85</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 60in deck - Model 74991  
60in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
88	<b>R323-23</b>	01-150-0810, 01-178-0636, 20-60-AGD, 323-23	Bolt - Hex HD 3/8-16 x 4-1/2	2	<b>2.45</b>	
<i>Tech Note: (2012-2019)-312000001-403319953:</i>						
89	<b>R51-4060</b>	51-4060	Bolt - Blade	3	<b>4.55</b>	
90	<b>R103-0865</b>	103-0865	Washer - Blade Bolt HD	3	<b>4.80</b>	
91	<b>R104-8301</b>	104-8301, 104-9301, 109-6658, 133-7570	Locknut - 3/8-16 Nylon Flanged	43	<b>0.84</b>	
<i>Tech Note: (2012-2019)-312000001-403319953:</i>						
93	<b>R119-8527</b>	119-1851, 119-8527	Spindle Shaft and Zerk Assy	3	<b>76.65</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
94	<b>R253-133</b>	253-133	Seal - Oil	6	<b>8.05</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
95	<b>R119-8558</b>	119-8558, 76-7500	Bearing - Ball - Special	6	<b>9.85</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
96	<b>R117-6184</b>	117-6184	Spacer	3	<b>7.50</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
97	<b>R119-8532</b>	114-8161, 119-8532	Snap Ring	3	<b>4.20</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
98	<b>R117-6172</b>	117-6172	Spindle Hub Assy w/Studs	3	<b>28.90</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 60in deck - Model 74991  
60in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
99	<b>R92-5836</b>	92-5836	Flat Washer - Hardened	3	<b>4.10</b>	
<i>Tech Note: (2010-2019)-310000001-403319953:</i>						
100	<b>R3296-67</b>	3296-67	Locknut - 3/4-16 Heavy Jam RH Thread	3	<b>3.75</b>	
<i>Tech Note: (2010-2019)-310000001-403319953:</i>						
101	<b>R471219</b>	30-8360, 302-2, 302-24, 302-31, 302-52, 471219	Zerk - Grease	3	<b>0.41</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
102	<b>R119-8560</b>	117-6157, 119-8560	Spindle Assy	3	<b>201.95</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
103	<b>R105-7734</b>	105-7734	Pulley - 7.75 in Dia with 1.75 Bore	3	<b>33.50</b>	
104	<b>R114-8195</b>	114-8195, R & R ONLY	Bolt- Ribbed Neck	18	<b>2.95</b>	
<i>Tech Note: (2010-2019)-310000001-403319953:</i>						
105	<b>R32128-43</b>	30-8990, 32128-43, 3290-357	Nut - Flanged Whiz - 3/8-16	2	<b>0.62</b>	
107	<b>R112-4212</b>	112-4212	Mount-Pulley	1	<b>9.25</b>	
108	<b>R323-11</b>	01-150-1440, 01-178-0618, 20-52-AD, 3224-7, 323-11	Bolt - 3/8-16 x 2 1/4 GR5	2	<b>0.84</b>	
109	<b>R104-0151</b>	104-0151	Spacer	1	<b>10.95</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 60in deck - Model 74991  
60in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
110	<b>R116-6317</b>	116-0133, 116-6317	Spring - Extension	1	<b>17.50</b>	
111	<b>R114-5867</b>	114-5867	Anchor - Spring - Tall	1	<b>12.05</b>	
112	<b>R121-8031-01</b>	121-8031-01	Plate-Skid	1	<b>36.20</b>	
117	<b>R3296-51</b>	3296-51, 3296-81	Nut - Nylon Lock 3/4-10 Gr 8	2	<b>5.70</b>	
118	<b>R1-633508</b>	1-633508	Washer - Spring Disc	6	<b>3.10</b>	
119	<b>R103-0063</b>	103-0063	Seal - Grease	4	<b>5.15</b>	
120	<b>R3233-34</b>	3233-34	Carriage Bolt - 1/2-13 x 2 1/2 Grade 5	3	<b>7.15</b>	
121	<b>R103-2768</b>	103-2768	Guard - Seal	4	<b>3.45</b>	
122	<b>R103-3051</b>	103-3051	Spacer - Nut - Hardened	4	<b>7.45</b>	
123	<b>RF5003</b>	32127-29, 32131-5, 32132-5, 3296-23	Locknut - ESNA 1/2-13	2	<b>0.78</b>	
125	<b>R116-0797-03</b>	116-0797-03	Link-Lift - Deck	1	<b>78.60</b>	
126	<b>R116-0780</b>	116-0780	Bolt - Hx HD Fl Shoulder	2	<b>8.45</b>	
127	<b>R453022</b>	01-166-0480, 01-166-1220, 21-3880, 217-21, 30-8550, 30-9110, 3256-28, 3256-44, 46-9030, Mar-71	Washer - 3/4 SAE	2	<b>0.43</b>	
128	<b>R32128-23</b>	32128-23, 3218-23, 99-5107	Nut - Lock Hex Flanged 1/2-13	6	<b>1.45</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 60in deck - Model 74991  
60in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
129	<b>R109-5010</b>	109-5010	Spacer	6	<b>3.65</b>	
130	<b>R109-5009</b>	109-5009	Bushing - Suspension - Rubber	6	<b>2.95</b>	
131	<b>R325-12</b>	01-150-0320, 01-150-0880, 01-178-0824, 20-93-AD, 325-12	Bolt - Hx HD	2	<b>5.35</b>	
132	<b>R103-5156</b>	103-5156	Axle- Caster	2	<b>9.65</b>	
133	<b>R325-17</b>	01-150-0640, 01-150-0850, 01-178-0832, 01-178-0836, 20-97-AGD, 325-17, 325-18, 48-9260	Bolt - Hex Head	1	<b>2.75</b>	
134	<b>R32128-37</b>	32128-37	Nut - 7-16-14 Hx Serr Fl	2	<b>3.25</b>	
135	<b>R109-5013</b>	109-5013	Panhard Rod Assy	1	<b>76.35</b>	
136	<b>R109-7952</b>	109-7952	Deck Strut Assy	2	<b>76.70</b>	
137	<b>R106-3216-01</b>	106-3216-01	Baffle - Discharge	1	<b>15.20</b>	
138	<b>R116-8888</b>	103-1474-01, 116-6707-01, 116-8888	Fork - Caster 7.875 in Inside	2	<b>110.10</b>	
139	<b>R116-5647</b>	116-5647	Seal - Grease	2	<b>3.05</b>	
140	<b>R325-39</b>	325-39	Bolt - Hx HD 1/2-13 x 9 1/2	2	<b>9.05</b>	
141	<b>R254-94</b>	1-543509, 254-94, 32-8090, 32-8240, 32-9640, 40440, 62-3330	Tapered Bearing Cone	4	<b>7.15</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 60in deck - Model 74991  
60in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
142	<b>R254-72</b>	01-103-0050, 01-103-0120, 01-103-0140, 1-543508, 254-71, 254-72, 40439, 62-3340, 99-4511	Cup - Bearing	4	<b>3.85</b>	
143	<b>R254-78</b>	01-102-0060, 01-102-0130, 1-633585, 254-78, 32-7790, 32-9580, 93-4813	Tapered Bearing Cone	4	<b>6.05</b>	
144	<b>R126-2475-03</b>	116-2217-03, 126-2475-03	Decklift - Front	1	<b>113.95</b>	
145	<b>R116-0459-03</b>	116-0459-03	Lift - Rear Deck	1	<b>193.20</b>	
146	<b>R114-5870</b>	114-5870	Idler Arm Assy with Bushings	1	<b>117.15</b>	
147	<b>R1-303514</b>	1-303514	Bearing - Flanged	2	<b>13.15</b>	
148	<b>R116-0000</b>	116-0000	Spring - Extension	1	<b>72.50</b>	
149	<b>R109-9066</b>	109-9066	Yoke - Adjust - Deck	4	<b>4.80</b>	
150	<b>R103-4882</b>	103-4882	Grease Cap - Castor	2	<b>4.20</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.