




Replaces John Deere 648M Quik-Trak Stand-On Mower Parts

Rotary Mower
48in Deck Parts



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces John Deere 648M Quik-Trak Stand-On Mower Parts

Rotary Mower
48in Deck Parts



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Price Each | Order Quantity |
|---------|--------------|--------------|-------------|---------|------------|----------------|
|---------|--------------|--------------|-------------|---------|------------|----------------|

Blades

| | | | | | | |
|---|---------------------|----------|---|---|--------------|--|
| 1 | RRB3065-1602 | TCU37209 | Mower Blade - High-Lift 16.5 x 2.5in x 5/8 Mt Hole | 3 | 12.65 | |
|---|---------------------|----------|---|---|--------------|--|

Detail Description: R&R Products rotary blades are manufactured in the USA with superior alloy steel and hardened for extended life. Lifetime guaranteed against defects in material and workmanship.:

| | | | | | | |
|---|---------------------|---------|---|---|--------------|--|
| 2 | RRB5360-1602 | UC10751 | Mower Blade - Wave Mulcher 16.5 x 2.5in x 5/8 Mt Hole | 3 | 13.85 | |
|---|---------------------|---------|---|---|--------------|--|

Belts

| | | | | | | |
|----|-------------------|----------------------|-----------------|---|--------------|--|
| 20 | RTCUC37189 | TCU37189, UC18232 | Belt - Hyd Pump | 1 | 33.25 | |
|----|-------------------|----------------------|-----------------|---|--------------|--|

| | | | | | | |
|----|-------------------|----------|-------------------|---|--------------|--|
| 21 | RTCUC34217 | TCU34217 | Belt - Deck - B49 | 1 | 41.65 | |
|----|-------------------|----------|-------------------|---|--------------|--|

Other Parts Available

| | | | | | | |
|----|-------------------|----------------------|-----------------|---|--------------|--|
| 80 | RTCUC40290 | TCU40290, UC14507 | Shaft - Spindle | 3 | 75.15 | |
|----|-------------------|----------------------|-----------------|---|--------------|--|

| | | | | | | |
|----|----------------|--------|---------------------|---|-------------|--|
| 81 | RC17964 | C17964 | Ring - Retaining HD | 3 | 4.45 | |
|----|----------------|--------|---------------------|---|-------------|--|

| | | | | | | |
|----|-------------------|----------------------|-------------------|---|--------------|--|
| 82 | RTCUC40287 | TCU40287, UC13505 | Retainer - Grease | 3 | 17.20 | |
|----|-------------------|----------------------|-------------------|---|--------------|--|

| | | | | | | |
|----|-------------------|----------|--------|---|-------------|--|
| 83 | RTCUC37610 | TCU37610 | Washer | 4 | 2.65 | |
|----|-------------------|----------|--------|---|-------------|--|

| | | | | | | |
|----|-----------------|---------|-------------------------|---|-------------|--|
| 85 | R14M7396 | 14M7396 | Locknut - Flanged Nyloc | 2 | 0.72 | |
|----|-----------------|---------|-------------------------|---|-------------|--|

| | | | | | | |
|----|-------------------|----------|---------|---|--------------|--|
| 86 | RTCUC34197 | TCU34197 | Bearing | 4 | 11.40 | |
|----|-------------------|----------|---------|---|--------------|--|

| | | | | | | |
|----|-------------------|----------|--------|---|--------------|--|
| 87 | RTCUC37595 | TCU37595 | Pulley | 1 | 56.85 | |
|----|-------------------|----------|--------|---|--------------|--|

| | | | | | | |
|----|-------------------|----------------------|----------------------|---|--------------|--|
| 88 | RTCUC18744 | TCU18744, UC28193 | Wheel - 5 in x 2 3/4 | 2 | 12.75 | |
|----|-------------------|----------------------|----------------------|---|--------------|--|

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.