




## Replaces Exmark Pioneer S-Series Parts

Zero-Turn Mower with 44 in Deck - Models PNS20KA443,  
PNS600KA443, PNS710KC443  
44in Deck



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Exmark Pioneer S-Series Parts

Zero-Turn Mower with 44 in Deck - Models PNS20KA443,  
PNS600KA443, PNS710KC443  
44in Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
<b>Tires</b>						
30	<b>R103-8415</b>	103-8415	Roller - Anti Scalp	2	<b>13.50</b>	
<i>Tech Note: Use only for model PNS710KC443:</i>						
31	<b>R68-2730</b>	1-603299	Wheel - Anti Scalp	2	<b>7.85</b>	
32	<b>R116-9981</b>	116-9981	Kit - Anti-Scalp Roller	2	<b>26.95</b>	
<i>Tech Note: Use only for model PNS710KC443:</i>						
33	<b>R109-6388</b>	109-6388	Roller Kit - Anti Scalp	2	<b>15.25</b>	
<i>Tech Note: Use only for model PNS20KA443:</i>						
<b>Other Parts Available</b>						
40	<b>R116-4669</b>	116-4669	Idler Pulley - Flat	1	<b>54.40</b>	
41	<b>R1-633447</b>	1-633447	Chain - Deck Lift	4	<b>6.75</b>	
42	<b>R116-6317</b>	116-0133, 116-6317	Spring - Extension	1	<b>17.50</b>	
43	<b>R104-8301</b>	104-8301, 109-6658	Locknut - 3/8-16 Nylon Flanged	20	<b>0.88</b>	
44	<b>R116-8131</b>	116-8131	Axle - Roller	2	<b>10.75</b>	
45	<b>R98-5975</b>	98-5975	Washer - Belleville	2	<b>2.40</b>	
46	<b>R116-3344</b>	116-3344	Spindle Housing Assy	2	<b>92.80</b>	
47	<b>R116-0720</b>	116-0720	Bearing - Ball - Special Triple Seal	4	<b>9.30</b>	
48	<b>R116-7306</b>	116-7306	Hex Nut - 3/4-16 with Nyloc	2	<b>2.90</b>	
49	<b>R103-3037</b>	103-3037	Splined Bushing	2	<b>15.55</b>	
50	<b>R112-3977</b>	112-3977	Bolt- Shoulder	2	<b>7.30</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Exmark Pioneer S-Series Parts

Zero-Turn Mower with 44 in Deck - Models PNS20KA443,  
PNS600KA443, PNS710KC443  
44in Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
51	<b>R99-2842</b>	99-2842	Spacer - Wheel	2	<b>16.25</b>	
52	<b>R32128-43</b>	32128-43, 3290-357	Nut - Flanged Whiz - 3/8-16	2	<b>0.65</b>	
53	<b>R109-9220</b>	109-9220	Bolt - Sems 1/2-20	2	<b>5.59</b>	
54	<b>R116-9362</b>	116-9362	Bolt - Hex HD 3/8-16 x 3 3/4 GR8 YZ	2	<b>1.22</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.