




Replaces John Deere 1545 Rotary Mower Parts

62in & 72in Side & Rear Discharge Deck - Models 2814
60in Deck Parts



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces John Deere 1545 Rotary Mower Parts

62in & 72in Side & Rear Discharge Deck - Models 2814
60in Deck Parts



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
---------	--------------	--------------	-------------	---------	------------	----------------

Rotary Blades

1	RTCU15882	M143749, TCU15882	Mower Blade - High Lift - 25 x 3 x 1/4 w/.910 Hole	3	18.95	
---	------------------	----------------------	--	---	--------------	--

Tech Note: Fits Model 2814:

1	RTCU15882M		Mower Blade - Mulching - 25 x 3 x 1/4 w/.910 Hole	3	31.95	
---	-------------------	--	---	---	--------------	--

Tech Note: Fits Model 2814:

Belts

20	RTCU19900	TCU19900	Belt - V - Fits 72 in Decks	1	109.65	
----	------------------	----------	-----------------------------	---	---------------	--

Detail Description: Fits Model 2814 Only:

20	RTCU19067	TCU19067	V-Belt - (Export Road Homologation) (Use with TCA15323)	1	178.75	
----	------------------	----------	---	---	---------------	--

20	RTCU13402	TCU13402	V-Belt - (Export)	1	154.50	
----	------------------	----------	-------------------	---	---------------	--

Other Parts Available

42	RTCU18744	TCU18744, UC28193	Wheel - 5 in x 2 3/4	2	12.75	
----	------------------	----------------------	----------------------	---	--------------	--

43	RAM125172	AM125172	Wheel Kit - Gage Wheel	1	32.25	
----	------------------	----------	------------------------	---	--------------	--

44	RM141764	M141764	Eyebolt - Includes Flanged Locknut	1	7.45	
----	-----------------	---------	------------------------------------	---	-------------	--

76	RM127353	M127353	Bushing	3	6.48	
----	-----------------	---------	---------	---	-------------	--

77	R253-133	M85699	Seal - Oil	3	8.05	
----	-----------------	--------	------------	---	-------------	--

78	RM88251	M169375, M88251	Bearing - Spindle	6	13.60	
----	----------------	--------------------	-------------------	---	--------------	--

79	RM127198	M127198	Seal	3	7.15	
----	-----------------	---------	------	---	-------------	--

80	R19M7489	19M7489	Bolt Hex HD - M16 x 45 Gr 10.9	3	4.50	
----	-----------------	---------	--------------------------------	---	-------------	--

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces John Deere 1545 Rotary Mower Parts

62in & 72in Side & Rear Discharge Deck - Models 2814
60in Deck Parts



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
81	RM115245	M115245	Roller	4	29.95	
82	RM123522	M123522	Washer - Belleville - Blade Bolt	3	13.95	
83	RM123520	M123520	Washer - Hardened	3	1.10	
84	RTC19299	TCU19299	Axle Bushing	2	19.75	
85	R19M8006	19M8006	Bolt - M8-1.25 x 120 Hx HD FI CI 10.9	2	5.85	
86	R14M7396	14M7396	Locknut - Flanged Nyloc	32	0.72	
87	RTCA17524	TCA17524	Idler Pulley - 5 in Flat Dia with .75 in Brg ID	2	35.30	
88	RM141695	M112398, M141695	Idler - North America (Replaces M112398)	1	170.15	
89	RAM129501	AM129501	Arm	1	66.45	
90	RM134382	M134382	Spindle - 25 mm w/M12-1.75 Blade Bolt Thrd	3	49.25	
91	RM110057	M110057	Shaft - Roller	2	44.90	
92	R24M7226	24M7226	Washer - 13 x 35 x 5 mm	1	3.35	
93	RTC51223	TCU51223	Deflector - Grass	3	24.70	
94	RTC38142	TCU14182, TCU38142	Hub - Sub For TCU51119 or TCU14182	3	70.90	
95	RM136044	M136044	Spring - Extension	1	14.85	
96	RM133598	M133598	Shield	2	11.95	
97	R14M7400	14M7400	Locknut - 10mm	3	1.05	
98	RTCA13570	TCA13570	Bracket	1	78.20	
99	R24H1308	24H1308	Washer	1	2.50	
100	R14M7167	14M7167	Nut - M10-1.5 Lock Nylon Insert	1	1.30	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces John Deere 1545 Rotary Mower Parts

62in & 72in Side & Rear Discharge Deck - Models 2814
60in Deck Parts



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
101	RM163058	M127517, M163058	Bushing - Sub For M127517	3	18.65	
103	R93-2559	TCU23201	Bearing	2	11.50	
104	RM132309	M132309	Spacer	2	9.25	
105	RM163060	M133398, M163060	Washer - Replaces RM133398	3	6.40	
106	RM123569	M123569	Flange Nut	3	6.90	
107	R19M7868	19M7868	Bolt - M8-1.25 x 30 HHF	30	1.60	
108	RM163053	M134305, M163053	Grass Deflector - Spindle	3	12.35	
109	R03M7184	03M7184	Bolt - Carriage M8	4	0.49	
110	RR50647	J16931, R50647	Pin - Hair Cotter	1	0.82	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.