




## Replaces Exmark Lazer Z X-Series Parts

Zero Turn Mower with 52in Deck - Models LZX740EKC526T0,

LZX740EKC526W0

Lift & Motion Control



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Exmark Lazer Z X-Series Parts

Zero Turn Mower with 52in Deck - Models LZX740EKC526T0,

LZX740EKC526W0

Lift & Motion Control



| Item No                                              | R&R Part No.        | OEM Part No.         | Description                      | Qty Req | Price Each   | Order Quantity |
|------------------------------------------------------|---------------------|----------------------|----------------------------------|---------|--------------|----------------|
| <b>Other parts</b>                                   |                     |                      |                                  |         |              |                |
| 74                                                   | <b>R109-5891</b>    | 109-5891             | Hub -Threaded                    | 2       | <b>11.30</b> |                |
| 76                                                   | <b>R1-323245</b>    | 1-323245             | Spring - Compression             | 4       | <b>4.45</b>  |                |
| 77                                                   | <b>R109-7124</b>    | 109-7124             | Spring - Extension               | 1       | <b>4.40</b>  |                |
| 78                                                   | <b>R116-0039</b>    | 116-0039             | Lever - Motion Control - RH      | 1       | <b>34.60</b> |                |
| 79                                                   | <b>R116-0040</b>    | 116-0040             | Lever - Motion Control - LH      | 1       | <b>34.25</b> |                |
| 80                                                   | <b>R116-0027</b>    | 116-0027             | Damper Control                   | 2       | <b>82.90</b> |                |
| 81                                                   | <b>R109-5668</b>    | 109-5668             | Grip - Control Lever - Foam      | 2       | <b>11.45</b> |                |
| 82                                                   | <b>R109-8107</b>    | 109-8107             | Pump Linkage Rear Assembly       | 2       | <b>55.75</b> |                |
| 83                                                   | <b>R1-543017</b>    | 1-543017             | Balljoint - RH                   | 2       | <b>18.10</b> |                |
| 84                                                   | <b>R1-633152</b>    | 1-633152             | Balljoint - LH                   | 2       | <b>18.10</b> |                |
| 87                                                   | <b>R116-0797-03</b> | 116-0797-03          | Link-Lift - Deck                 | 1       | <b>78.60</b> |                |
| 88                                                   | <b>R116-0886</b>    | 116-0886             | Spring - Extension               | 1       | <b>86.85</b> |                |
| 89                                                   | <b>R32128-23</b>    | 32128-23,<br>99-5107 | Nut - Lock Hex Flanged 1/2-13    | 12      | <b>1.55</b>  |                |
| 90                                                   | <b>R453022</b>      | 3256-28              | Washer - 3/4 SAE                 | 2       | <b>0.43</b>  |                |
| 91                                                   | <b>R116-0780</b>    | 116-0780             | Bolt - Hx HD Fl Shoulder         | 2       | <b>8.45</b>  |                |
| <b>Tech Note: Use only for model LZX801GKA526Q1:</b> |                     |                      |                                  |         |              |                |
| 91                                                   | <b>R116-2022</b>    | 116-2022             | Shoulder Bolt - Flanged Hex Head | 2       | <b>5.35</b>  |                |
| 92                                                   | <b>R109-7952</b>    | 109-7952             | Deck Strut Assy                  | 2       | <b>76.70</b> |                |
| 93                                                   | <b>R109-5013</b>    | 109-5013             | Panhard Rod Assy                 | 1       | <b>76.35</b> |                |
| 94                                                   | <b>R109-5010</b>    | 109-5010             | Spacer                           | 6       | <b>3.65</b>  |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Exmark Lazer Z X-Series Parts

Zero Turn Mower with 52in Deck - Models LZX740EKC526T0,

LZX740EKC526W0

Lift & Motion Control



| Item No | R&R Part No.     | OEM Part No.                  | Description                            | Qty Req | Price Each  | Order Quantity |
|---------|------------------|-------------------------------|----------------------------------------|---------|-------------|----------------|
| 95      | <b>R109-5009</b> | 109-5009                      | Bushing - Suspension - Rubber          | 6       | <b>2.95</b> |                |
| 96      | <b>R325-12</b>   | 325-12                        | Bolt - Hx HD                           | 2       | <b>5.35</b> |                |
| 97      | <b>R3233-34</b>  | 3233-34                       | Carriage Bolt - 1/2-13 x 2 1/2 Grade 5 | 3       | <b>7.15</b> |                |
| 98      | <b>R325-17</b>   | 325-17                        | Bolt - Hex Head                        | 1       | <b>2.90</b> |                |
| 99      | <b>R92-7674</b>  | 92-7674                       | Bolt - Shoulder                        | 1       | <b>2.75</b> |                |
| 100     | <b>R104-8300</b> | 104-8300,<br>119-4041         | Locknut - 5/16-18 Flanged Y/Zinc       | 6       | <b>0.49</b> |                |
| 101     | <b>R104-8301</b> | 104-8301,<br>109-6658         | Locknut - 3/8-16 Nylon Flanged         | 4       | <b>0.88</b> |                |
| 102     | <b>R400264</b>   | 323-29,<br>323-7              | Bolt - Hex HD 3/8-16 x 1-1/4           | 4       | <b>0.42</b> |                |
| 103     | <b>R115-1794</b> | 115-1794                      | Bolt - Hx HD Fl 5/16-18 x 1 1/2        | 2       | <b>1.55</b> |                |
| 104     | <b>R453009</b>   | 3256-2,<br>3256-3,<br>3256-67 | Washer - Flat 5/16 SAE                 | 2       | <b>0.14</b> |                |
| 105     | <b>R3219-2</b>   | 3219-2                        | Nut - 5/16-24 Zinc                     | 4       | <b>0.39</b> |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.