




Replaces Toro Titan MX 6080 Parts

Zero Turn Mower with 60in Deck - Model 74873

Traction Drive Assembly



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Titan MX 6080 Parts

Zero Turn Mower with 60in Deck - Model 74873

Traction Drive Assembly

OEM



Item No	R&R Part No.	Part No.	Description	Qty Req	Price Each	Order Quantity
---------	--------------	----------	-------------	---------	------------	----------------

Belts

10	R115-9613	115-9613	Belt - Cogged V	1	34.05	
----	------------------	----------	-----------------	---	--------------	--

Other Parts Available

70	R109-3397	109-3397	Pulley - Idler - Flat 3.5 in	2	15.55	
----	------------------	----------	------------------------------	---	--------------	--

71	R117-5350	117-5350	Idler Arm	1	19.15	
----	------------------	----------	-----------	---	--------------	--

72	R110-9981	110-9981	Washer-Plain	1	10.85	
----	------------------	----------	--------------	---	--------------	--

73	R101526	01-150-0970, 01-178-0620, 20-53-AGD, 321-11, 3224-8, 323-11, 323-12, 323-31, 323-4, 323-47	Bolt - Hex HD 3/8-16 x 2-1/2 GR5	1	0.96	
----	----------------	---	----------------------------------	---	-------------	--

74	R104-8301	104-8301, 104-9301, 109-6658, 133-7570	Locknut - 3/8-16 Nylon Flanged	3	0.88	
----	------------------	---	--------------------------------	---	-------------	--

75	R3231-4	01-157-0440, 01-173-0612, 3231-4	Bolt - Carriage 3/8-16 x 1-1/2	1	1.30	
----	----------------	--	--------------------------------	---	-------------	--

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.