




Replaces Toro Z Master 2000 Parts

Zero Turn Mower with 60in Deck - Model 74145
60in Side Discharge Deck



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master 2000 Parts

Zero Turn Mower with 60in Deck - Model 74145

60in Side Discharge Deck



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Price Each | Order Quantity |
|------------------------------|---------------------|---|--|---------|---------------|----------------|
| Belts | | | | | | |
| 20 | R114-5858 | 114-5858 | Belt - V - Deck | 1 | 120.65 | |
| Blades | | | | | | |
| 30 | R115-9649-03 | 115-9649-03 | Mower Blade - 20.5 in High-Flow | 3 | 20.85 | |
| Tires | | | | | | |
| 40 | R68-2730 | 1-603299, 68-2730 | Wheel - Anti Scalp | 4 | 7.85 | |
| 41 | RCT5121861 | 1-523009, 126-5959 | Tire - 13x6.50-6 Nhs (4 Ply) Carlisle Smooth | 2 | 39.80 | |
| 42 | R127-9540 | 127-9540 | Tire & Wheel - 13x6.50-6 Pneumatic | 2 | 152.80 | |
| 42 | R117-0361 | 117-0361 | Wheel & Tire Assy 13x6.50-6 Pneumatic | 1 | 147.75 | |
| Other Parts Available | | | | | | |
| 70 | R116-0797-03 | 116-0797-03 | Link-Lift - Deck | 1 | 78.60 | |
| 71 | R116-0780 | 116-0780 | Bolt - Hx HD Fl Shoulder | 2 | 8.45 | |
| 72 | R453022 | 01-166-0480, 01-166-1220, 21-3880, 217-21, 30-8550, 30-9110, 3256-28, 3256-44, 46-9030, Mar-71 | Washer - 3/4 SAE | 2 | 0.43 | |
| 73 | R126-2475-03 | 116-2217-03, 126-2475-03 | Decklift - Front | 1 | 113.95 | |
| 74 | R116-0459-03 | 116-0459-03 | Lift - Rear Deck | 1 | 193.20 | |
| 75 | R104-8301 | 104-8301, 104-9301, 109-6658, 133-7570 | Locknut - 3/8-16 Nylon Flanged | 24 | 0.84 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master 2000 Parts

Zero Turn Mower with 60in Deck - Model 74145

60in Side Discharge Deck



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Price Each | Order Quantity |
|---------|---------------------|--|--------------------------------|---------|--------------|----------------|
| 76 | R3231-4 | 01-157-0440, 01-173-0612, 3231-4 | Bolt - Carriage 3/8-16 x 1-1/2 | 2 | 1.20 | |
| 77 | R32128-37 | 32128-37 | Nut - 7-16-14 Hx Serr Fl | 1 | 3.25 | |
| 78 | R116-6317 | 116-0133, 116-6317 | Spring - Extension | 1 | 17.50 | |
| 79 | R114-5867 | 114-5867 | Anchor - Spring - Tall | 1 | 12.05 | |
| 80 | R1-303514 | 1-303514 | Bearing - Flanged | 2 | 13.15 | |
| 81 | R104-0151 | 104-0151 | Spacer | 1 | 10.95 | |
| 82 | R323-11 | 01-150-1440, 01-178-0618, 20-52-AD, 3224-7, 323-11 | Bolt - 3/8-16 x 2 1/4 GR5 | 2 | 0.84 | |
| 83 | R112-4212 | 112-4212 | Mount-Pulley | 1 | 9.25 | |
| 84 | R108-4059-01 | 108-4059-01 | Plate-Hinge, Rear | 1 | 22.95 | |
| 85 | R106-3253-01 | 106-3253-01 | Plate-Hinge, Front | 1 | 22.95 | |
| 86 | R106-3246-01 | 106-3246-01 | Deflector | 1 | 37.35 | |
| 87 | R108-4052 | 108-4052 | Spring - Torsion | 1 | 14.60 | |
| 88 | R106-3248-03 | 106-3248-03 | Strap - Discharge | 1 | 14.20 | |
| 90 | R151416 | 108-5029, 110-0759, 151416 | Deflector - Long | 1 | 37.35 | |
| 91 | R322-50 | 322-50 | Bolt - Hx HD 5/16-18 x 7 1/2 | 1 | 3.75 | |
| 92 | R3296-47 | 3296-47 | Locknut - 5/16-18 Jam Nyloc | 1 | 0.59 | |
| 93 | R3231-27 | 3231-27 | Bolt - Carriage 3/8-16 x 7/8 | 6 | 0.53 | |
| 94 | R106-3216-01 | 106-3216-01 | Baffle - Discharge | 1 | 15.20 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master 2000 Parts

Zero Turn Mower with 60in Deck - Model 74145

60in Side Discharge Deck



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Price Each | Order Quantity |
|---------|------------------|--|------------------------------------|---------|--------------|----------------|
| 95 | R98-5967 | 98-5967 | Spacer-Wheel | 1 | 10.35 | |
| 96 | R108-5388 | 108-5388 | Bolt - Hx HD 3/8-16 x 7 1/2 | 1 | 9.25 | |
| 97 | R98-7913 | 98-7913 | Spacer - Tube | 2 | 5.80 | |
| 98 | R98-7912 | 98-7912 | Bushing - Spanner Wheel | 2 | 5.85 | |
| 99 | R323-23 | 01-150-0810, 01-178-0636, 20-60-AGD, 323-23 | Bolt - Hex HD 3/8-16 x 4-1/2 | 2 | 2.45 | |
| 100 | R3296-51 | 3296-51, 3296-81 | Nut - Nylon Lock 3/4-10 Gr 8 | 2 | 5.70 | |
| 101 | R1-633508 | 1-633508 | Washer - Spring Disc | 6 | 3.10 | |
| 102 | R254-94 | 1-543509, 254-94, 32-8090, 32-8240, 32-9640, 40440, 62-3330 | Tapered Bearing Cone | 4 | 7.15 | |
| 103 | R254-72 | 01-103-0050, 01-103-0120, 01-103-0140, 1-543508, 254-71, 254-72, 40439, 62-3340, 99-4511 | Cup - Bearing | 4 | 3.85 | |
| 104 | R116-5647 | 116-5647 | Seal - Grease | 2 | 3.05 | |
| 105 | R325-37 | 325-36, 325-37 | Bolt - Hex Head 1/2-13 x 7 Grade 5 | 2 | 4.80 | |
| 106 | R103-2768 | 103-2768 | Guard - Seal | 4 | 3.45 | |
| 107 | R103-0063 | 103-0063 | Seal - Grease | 4 | 5.15 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Z Master 2000 Parts

Zero Turn Mower with 60in Deck - Model 74145

60in Side Discharge Deck



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Price Each | Order Quantity |
|---------|------------------|---|---|---------|---------------|----------------|
| 108 | R254-78 | 01-102-0060, 01-102-0130, 1-633585, 254-78, 32-7790, 32-9580, 93-4813 | Tapered Bearing Cone | 4 | 6.05 | |
| 109 | R126-5360 | 126-5360 | Axle- Caster w/Spacer Nut | 2 | 18.15 | |
| 110 | R103-3051 | 103-3051 | Spacer - Nut - Hardened | 4 | 7.45 | |
| 111 | R103-3155 | 103-3155 | Axle - Caster | 2 | 21.05 | |
| 112 | RF5003 | 32127-29, 32131-5, 32132-5, 3296-23 | Locknut - ESNA 1/2-13 | 2 | 0.78 | |
| 113 | R116-8883 | 1-632511-01, 116-8883 | Caster Fork Assy Incl Seal 6.25 in Inside | 2 | 105.85 | |
| 113 | R116-8888 | 103-1474-01, 116-6707-01, 116-8888 | Fork - Caster 7.875 in Inside | 1 | 110.10 | |
| 114 | R120-2505 | 120-2505 | Spindle Shaft | 3 | 32.30 | |
| 115 | R120-7856 | 120-7856 | Pulley B Section 7.75 in w/25mm Bore | 3 | 41.95 | |
| 116 | R3296-67 | 3296-67 | Locknut - 3/4-16 Heavy Jam RH Thread | 3 | 3.75 | |
| 117 | R92-5836 | 92-5836 | Flat Washer - Hardened | 3 | 4.10 | |
| 118 | R51-4060 | 51-4060 | Bolt - Blade | 3 | 4.55 | |
| 119 | R116-0720 | 116-0720 | Bearing - Ball - Special Triple Seal | 6 | 9.30 | |
| 120 | R115-2641 | 115-2641 | Spacer- Bearing | 3 | 8.45 | |
| 121 | R109-8590 | 109-8590 | Pulley - Idler | 1 | 112.95 | |
| 122 | R120-2451 | 120-2451, 121-5960 | Deflector Assy | 1 | 95.45 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.