




# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 74901  
48in Side Discharge Deck



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 74901  
48in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
<b>Belts</b>						
20	<b>R115-7407</b>	115-7407	Belt- V	1	<b>109.25</b>	
<b>Rotary Blades</b>						
30	<b>R107-3192-03</b>	107-3192-03	Mower Blade - 16.5 in High-Flow	3	<b>15.35</b>	
30	<b>R110-0414</b>	110-0414	Mower Blade Kit - 16.5 in High-Flow Set/6	1	<b>0.00</b>	
<b>Wheels</b>						
40	<b>R68-2730</b>	1-603299, 68-2730	Wheel - Anti Scalp	3	<b>7.85</b>	
41	<b>R109-9126</b>	109-9126	Tire & Wheel - 13x5.00-6 - White	2	<b>135.75</b>	
41	<b>R127-9531</b>	127-9531	Tire & Wheel - 13x5.00-6 - Grey	2	<b>148.60</b>	
<b>Other Parts Available</b>						
70	<b>R106-3253-01</b>	106-3253-01	Plate-Hinge, Front	1	<b>22.95</b>	
<i>Tech Note: (2012-2019)-312000001-404320000:</i>						
71	<b>R104-8301</b>	104-8301, 104-9301, 109-6658, 133-7570	Locknut - 3/8-16 Nylon Flanged	33	<b>0.84</b>	
<i>Tech Note: (2012-2019)-312000001-404320000:</i>						
72	<b>R108-4059-01</b>	108-4059-01	Plate-Hinge, Rear	1	<b>22.95</b>	
<i>Tech Note: (2012-2019)-312000001-404320000:</i>						
73	<b>R106-3246-01</b>	106-3246-01	Deflector	1	<b>37.35</b>	
<i>Tech Note: (2012-2019)-312000001-404320000:</i>						
74	<b>R151416</b>	108-5029, 110-0759, 151416	Deflector - Long	1	<b>37.35</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 74901  
48in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
<i>Tech Note: (2012-2019)-312000001-404320000:</i>						
75	<b>R106-3248-03</b>	106-3248-03	Strap - Discharge	1	<b>14.20</b>	
<i>Tech Note: (2012-2019)-312000001-404320000:</i>						
76	<b>R3231-4</b>	01-157-0440, 01-173-0612, 3231-4	Bolt - Carriage 3/8-16 x 1-1/2	4	<b>1.20</b>	
<i>Tech Note: (2012-2019)-312000001-404320000:</i>						
77	<b>R108-2792</b>	108-2792	Rubber Deflector Assy	1	<b>97.35</b>	
<i>Tech Note: (2012-2019)-312000001-404320000:</i>						
78	<b>R3296-47</b>	3296-47	Locknut - 5/16-18 Jam Nyloc	1	<b>0.59</b>	
79	<b>R108-4052</b>	108-4052	Spring - Torsion	1	<b>14.60</b>	
80	<b>R322-50</b>	322-50	Bolt - Hx HD 5/16-18 x 7 1/2	1	<b>3.75</b>	
81	<b>R98-5967</b>	98-5967	Spacer-Wheel	1	<b>10.35</b>	
82	<b>R108-5388</b>	108-5388	Bolt - Hx HD 3/8-16 x 7 1/2	1	<b>9.25</b>	
83	<b>R115-7455-01</b>	115-7455-01	Baffle Assy	1	<b>73.05</b>	
84	<b>R3231-27</b>	3231-27	Bolt - Carriage 3/8-16 x 7/8	2	<b>0.53</b>	
85	<b>R98-7913</b>	98-7913	Spacer - Tube	1	<b>5.80</b>	
86	<b>R98-7912</b>	98-7912	Bushing - Spanner Wheel	1	<b>5.85</b>	
87	<b>R323-23</b>	01-150-0810, 01-178-0636, 20-60-AGD, 323-23	Bolt - Hex HD 3/8-16 x 4-1/2	1	<b>2.45</b>	
88	<b>R51-4060</b>	51-4060	Bolt - Blade	3	<b>4.55</b>	
<i>Tech Note: (2010-2019)-310000001-404320000:</i>						

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 74901  
48in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
89	<b>R103-0865</b>	103-0865	Washer - Blade Bolt HD	3	<b>4.80</b>	
90	<b>R119-8527</b>	119-1851, 119-8527	Spindle Shaft and Zerk Assy	3	<b>76.65</b>	
<i>Tech Note: (2011-2016)-311000001-316000001:</i>						
91	<b>R253-133</b>	253-133	Seal - Oil	6	<b>8.05</b>	
<i>Tech Note: (2010-2019)-310000001-404320000:</i>						
92	<b>R119-8558</b>	119-8558, 76-7500	Bearing - Ball - Special	6	<b>9.85</b>	
<i>Tech Note: (2011-2016)-311000001-316000001:</i>						
93	<b>R117-6184</b>	117-6184	Spacer	3	<b>7.50</b>	
<i>Tech Note: (2010-2019)-310000001-404320000:</i>						
94	<b>R119-8532</b>	114-8161, 119-8532	Snap Ring	3	<b>4.20</b>	
<i>Tech Note: (2011-2016)-311000001-316000001:</i>						
95	<b>R117-6172</b>	117-6172	Spindle Hub Assy w/Studs	3	<b>28.90</b>	
<i>Tech Note: (2011-2016)-311000001-316000001:</i>						
96	<b>R92-5836</b>	92-5836	Flat Washer - Hardened	3	<b>4.10</b>	
<i>Tech Note: (2010-2019)-310000001-404320000:</i>						
97	<b>R3296-67</b>	3296-67	Locknut - 3/4-16 Heavy Jam RH Thread	3	<b>3.75</b>	
<i>Tech Note: (2010-2019)-310000001-404320000:</i>						
98	<b>R471219</b>	30-8360, 302-2, 302-24, 302-31, 302-52, 471219	Zerk - Grease	3	<b>0.41</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 74901  
48in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
<i>Tech Note: (2010-2019)-310000001-404320000:</i>						
100	<b>R119-8560</b>	117-6157, 119-8560	Spindle Assy	3	<b>201.95</b>	
<i>Tech Note: Serial #311000001 &amp; Up:</i>						
101	<b>R114-8195</b>	114-8195, R & R ONLY	Bolt- Ribbed Neck	18	<b>2.95</b>	
<i>Tech Note: (2010-2019)-310000001-404320000:</i>						
102	<b>R32128-43</b>	30-8990, 32128-43, 3290-357	Nut - Flanged Whiz - 3/8-16	3	<b>0.62</b>	
<i>Tech Note: (2010-2019)-310000001-404320000:</i>						
104	<b>R112-4212</b>	112-4212	Mount-Pulley	1	<b>9.25</b>	
105	<b>R323-11</b>	01-150-1440, 01-178-0618, 20-52-AD, 3224-7, 323-11	Bolt - 3/8-16 x 2 1/4 GR5	2	<b>0.84</b>	
106	<b>R104-0151</b>	104-0151	Spacer	1	<b>10.95</b>	
107	<b>R116-6317</b>	116-0133, 116-6317	Spring - Extension	1	<b>17.50</b>	
108	<b>R114-5867</b>	114-5867	Anchor - Spring - Tall	1	<b>12.05</b>	
109	<b>R109-7952</b>	109-7952	Deck Strut Assy	2	<b>76.70</b>	
110	<b>R109-5013</b>	109-5013	Panhard Rod Assy	1	<b>76.35</b>	
111	<b>R32128-37</b>	32128-37	Nut - 7-16-14 Hx Serr Fl	2	<b>3.25</b>	
112	<b>R116-0886</b>	116-0886	Spring - Extension	1	<b>86.85</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 74901  
48in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
113	<b>R325-17</b>	01-150-0640, 01-150-0850, 01-178-0832, 01-178-0836, 20-97-AGD, 325-17, 325-18, 48-9260	Bolt - Hex Head	1	<b>2.75</b>	
114	<b>R3233-34</b>	3233-34	Carriage Bolt - 1/2-13 x 2 1/2 Grade 5	3	<b>7.15</b>	
115	<b>R107-8541-01</b>	107-8541-01	Baffle - Discharge	1	<b>12.65</b>	
116	<b>R116-6702-01</b>	116-6702-01	Fork-Caster	2	<b>64.25</b>	
117	<b>R3296-51</b>	3296-51, 3296-81	Nut - Nylon Lock 3/4-10 Gr 8	2	<b>5.70</b>	
118	<b>R1-633508</b>	1-633508	Washer - Spring Disc	6	<b>3.10</b>	
119	<b>R103-0063</b>	103-0063	Seal - Grease	4	<b>5.15</b>	
120	<b>R325-42</b>	325-42	Bolt - 1/2-13 x 8 Hex Head Gr 5	2	<b>10.30</b>	
121	<b>R103-2768</b>	103-2768	Guard - Seal	4	<b>3.45</b>	
122	<b>R103-3051</b>	103-3051	Spacer - Nut - Hardened	4	<b>7.45</b>	
123	<b>RF5003</b>	32127-29, 32131-5, 32132-5, 3296-23	Locknut - ESNA 1/2-13	2	<b>0.78</b>	
124	<b>R103-3155</b>	103-3155	Axle - Caster	2	<b>21.05</b>	
125	<b>R116-0797-03</b>	116-0797-03	Link-Lift - Deck	1	<b>78.60</b>	
126	<b>R116-0780</b>	116-0780	Bolt - Hx HD Fl Shoulder	2	<b>8.45</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 74901  
48in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
127	<b>R453022</b>	01-166-0480, 01-166-1220, 21-3880, 217-21, 30-8550, 30-9110, 3256-28, 3256-44, 46-9030, Mar-71	Washer - 3/4 SAE	2	<b>0.43</b>	
128	<b>R32128-23</b>	32128-23, 3218-23, 99-5107	Nut - Lock Hex Flanged 1/2-13	8	<b>1.45</b>	
129	<b>R109-5010</b>	109-5010	Spacer	6	<b>3.65</b>	
130	<b>R109-5009</b>	109-5009	Bushing - Suspension - Rubber	6	<b>2.95</b>	
131	<b>R325-12</b>	01-150-0320, 01-150-0880, 01-178-0824, 20-93-AD, 325-12	Bolt - Hx HD	1	<b>5.35</b>	
132	<b>R1-543511</b>	1-543511	Seal- Grease	2	<b>7.90</b>	
<i>Tech Note: Up to Serial #313000001:</i>						
132	<b>R116-5647</b>	116-5647	Seal - Grease	2	<b>3.05</b>	
<i>Tech Note: Serial #313000001 &amp; Up:</i>						
133	<b>R254-94</b>	1-543509, 254-94, 32-8090, 32-8240, 32-9640, 40440, 62-3330	Tapered Bearing Cone	4	<b>7.15</b>	
134	<b>R112-4230-01</b>	112-4230-01	Plate- Skid	1	<b>49.10</b>	
<i>Tech Note: Up to Serial #314000001:</i>						

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.





# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 48in deck - Model 74901  
48in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
135	<b>R254-78</b>	01-102-0060, 01-102-0130, 1-633585, 254-78, 32-7790, 32-9580, 93-4813	Tapered Bearing Cone	4	<b>6.05</b>	
136	<b>R254-72</b>	01-103-0050, 01-103-0120, 01-103-0140, 1-543508, 254-71, 254-72, 40439, 62-3340, 99-4511	Cup - Bearing	4	<b>3.85</b>	
137	<b>R121-7975-01</b>	121-7975-01	Plate - Skid	1	<b>14.35</b>	
<i>Tech Note: Serial #314000001 &amp; Up:</i>						
139	<b>R1-613098</b>	1-613098	Pulley- Idler	1	<b>33.70</b>	
140	<b>R114-5862-01</b>	114-5862-01	Baffle	1	<b>96.05</b>	
141	<b>R116-0459-03</b>	116-0459-03	Lift - Rear Deck	1	<b>193.20</b>	
142	<b>R114-5870</b>	114-5870	Idler Arm Assy with Bushings	1	<b>117.15</b>	
143	<b>R1-303514</b>	1-303514	Bearing - Flanged	2	<b>13.15</b>	
144	<b>R109-9066</b>	109-9066	Yoke - Adjust - Deck	4	<b>4.80</b>	
145	<b>R103-4882</b>	103-4882	Grease Cap - Castor	2	<b>4.20</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.