




# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 74903  
52in Side Discharge Deck



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 74903  
52in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
<b>Belts</b>						
20	<b>R115-7426</b>	115-7426	Belt- V	1	<b>116.20</b>	
<b>Rotary Blades</b>						
30	<b>R105-7781-03</b>	105-7781-03	Mower Blade - 18 in High-Flow	3	<b>11.25</b>	
30	<b>R108-1117</b>	108-1117	Mower Blade Kit - 18 in High-Flow Set/6	1	<b>0.00</b>	
30	<b>R105-7779-03</b>	105-7779-03	Mower Blade - 18 in Recycler	3	<b>16.95</b>	
30	<b>R110-0408</b>	110-0408	Mower Blade Kit - 18 in Recycler Set/6	1	<b>0.00</b>	
<b>Wheels</b>						
40	<b>R68-2730</b>	1-603299, 68-2730	Wheel - Anti Scalp	3	<b>7.85</b>	
41	<b>R109-9127</b>	109-9125, 109-9127	Tire & Wheel - 13x6.50-6 Flat Free	2	<b>127.60</b>	
<b>Other Parts Available</b>						
70	<b>R106-3253-01</b>	106-3253-01	Plate-Hinge, Front	1	<b>22.95</b>	
<i>Tech Note: (2012-2019)-312000001-404971756:</i>						
71	<b>R104-8301</b>	104-8301, 104-9301, 109-6658, 133-7570	Locknut - 3/8-16 Nylon Flanged	44	<b>0.84</b>	
<i>Tech Note: (2011-2019)-311000001-404971756:</i>						
72	<b>R108-4059-01</b>	108-4059-01	Plate-Hinge, Rear	1	<b>22.95</b>	
<i>Tech Note: (2013-2019)-313000001-404971756:</i>						
73	<b>R106-3246-01</b>	106-3246-01	Deflector	1	<b>37.35</b>	
<i>Tech Note: (2012-2019)-312000001-404971756:</i>						

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 74903  
52in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
74	<b>R151416</b>	108-5029, 110-0759, 151416	Deflector - Long	1	<b>37.35</b>	
75	<b>R106-3248-03</b>	106-3248-03	Strap - Discharge	1	<b>14.20</b>	
76	<b>R3231-4</b>	01-157-0440, 01-173-0612, 3231-4	Bolt - Carriage 3/8-16 x 1-1/2	4	<b>1.20</b>	
<i>Tech Note: (2012-2019)-312000001-404971756:</i>						
77	<b>R108-2792</b>	108-2792	Rubber Deflector Assy	1	<b>97.35</b>	
<i>Tech Note: (2012-2019)-312000001-404971756:</i>						
78	<b>R3296-47</b>	3296-47	Locknut - 5/16-18 Jam Nyloc	1	<b>0.59</b>	
79	<b>R108-4052</b>	108-4052	Spring - Torsion	1	<b>14.60</b>	
80	<b>R322-50</b>	322-50	Bolt - Hx HD 5/16-18 x 7 1/2	1	<b>3.75</b>	
81	<b>R98-5967</b>	98-5967	Spacer-Wheel	1	<b>10.35</b>	
82	<b>R108-5388</b>	108-5388	Bolt - Hx HD 3/8-16 x 7 1/2	1	<b>9.25</b>	
83	<b>R115-7455-01</b>	115-7455-01	Baffle Assy	1	<b>73.05</b>	
84	<b>R3231-27</b>	3231-27	Bolt - Carriage 3/8-16 x 7/8	1	<b>0.53</b>	
85	<b>R98-7913</b>	98-7913	Spacer - Tube	1	<b>5.80</b>	
86	<b>R98-7912</b>	98-7912	Bushing - Spanner Wheel	1	<b>5.85</b>	
87	<b>R323-23</b>	01-150-0810, 01-178-0636, 20-60-AGD, 323-23	Bolt - Hex HD 3/8-16 x 4-1/2	1	<b>2.45</b>	
88	<b>R51-4060</b>	51-4060	Bolt - Blade	3	<b>4.55</b>	
<i>Tech Note: (2010-2019)-310000001-404971756:</i>						
89	<b>R103-0865</b>	103-0865	Washer - Blade Bolt HD	3	<b>4.80</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 74903  
52in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
90	<b>R119-8527</b>	119-1851, 119-8527	Spindle Shaft and Zerk Assy	3	<b>76.65</b>	
<i>Tech Note: (2011-2016)-311000001-316000001:</i>						
91	<b>R253-133</b>	253-133	Seal - Oil	6	<b>8.05</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
92	<b>R119-8558</b>	119-8558, 76-7500	Bearing - Ball - Special	6	<b>9.85</b>	
<i>Tech Note: (2011-2016)-311000001-316000001:</i>						
93	<b>R117-6184</b>	117-6184	Spacer	3	<b>7.50</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
94	<b>R119-8532</b>	114-8161, 119-8532	Snap Ring	3	<b>4.20</b>	
<i>Tech Note: (2011-2016)-311000001-316000001:</i>						
95	<b>R117-6172</b>	117-6172	Spindle Hub Assy w/Studs	3	<b>28.90</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
96	<b>R92-5836</b>	92-5836	Flat Washer - Hardened	3	<b>4.10</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
97	<b>R3296-67</b>	3296-67	Locknut - 3/4-16 Heavy Jam RH Thread	3	<b>3.75</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
98	<b>R471219</b>	30-8360, 302-2, 302-24, 302-31, 302-52, 471219	Zerk - Grease	3	<b>0.41</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 74903  
52in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
99	<b>R119-8560</b>	117-6157, 119-8560	Spindle Assy	3	<b>201.95</b>	
<i>Tech Note: (2011-2016)-311000001-316000001:</i>						
100	<b>R115-7450</b>	115-7450	Pulley - 6.75 in Dia with 1.75 Bore	3	<b>33.55</b>	
101	<b>R114-8195</b>	114-8195, R & R ONLY	Bolt- Ribbed Neck	18	<b>2.95</b>	
<i>Tech Note: (2010-2016)-310000001-316000001:</i>						
102	<b>R32128-43</b>	30-8990, 32128-43, 3290-357	Nut - Flanged Whiz - 3/8-16	3	<b>0.62</b>	
103	<b>R112-4212</b>	112-4212	Mount-Pulley	1	<b>9.25</b>	
104	<b>R323-11</b>	01-150-1440, 01-178-0618, 20-52-AD, 3224-7, 323-11	Bolt - 3/8-16 x 2 1/4 GR5	2	<b>0.84</b>	
105	<b>R104-0151</b>	104-0151	Spacer	1	<b>10.95</b>	
106	<b>R116-6317</b>	116-0133, 116-6317	Spring - Extension	1	<b>17.50</b>	
<i>Tech Note: (2013-2019)-313000001-404971756:</i>						
107	<b>R114-5867</b>	114-5867	Anchor - Spring - Tall	1	<b>12.05</b>	
108	<b>R116-8888</b>	103-1474-01, 116-6707-01, 116-8888	Fork - Caster 7.875 in Inside	2	<b>110.10</b>	
109	<b>R1-633508</b>	1-633508	Washer - Spring Disc	6	<b>3.10</b>	
110	<b>R103-3051</b>	103-3051	Spacer - Nut - Hardened	4	<b>7.45</b>	
111	<b>R103-2768</b>	103-2768	Guard - Seal	4	<b>3.45</b>	
112	<b>R103-0063</b>	103-0063	Seal - Grease	4	<b>5.15</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 74903  
52in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
113	<b>R103-5156</b>	103-5156	Axle- Caster	2	<b>9.65</b>	
114	<b>R325-39</b>	325-39	Bolt - Hx HD 1/2-13 x 9 1/2	2	<b>9.05</b>	
115	<b>R3296-51</b>	3296-51, 3296-81	Nut - Nylon Lock 3/4-10 Gr 8	2	<b>5.70</b>	
116	<b>R107-8541-01</b>	107-8541-01	Baffle - Discharge	1	<b>12.65</b>	
117	<b>R254-94</b>	1-543509, 254-94, 32-8090, 32-8240, 32-9640, 40440, 62-3330	Tapered Bearing Cone	4	<b>7.15</b>	
118	<b>R1-543511</b>	1-543511	Seal- Grease	2	<b>7.90</b>	
119	<b>RF5003</b>	32127-29, 32131-5, 32132-5, 3296-23	Locknut - ESNA 1/2-13	2	<b>0.78</b>	
120	<b>R109-7952</b>	109-7952	Deck Strut Assy	2	<b>76.70</b>	
121	<b>R109-5013</b>	109-5013	Panhard Rod Assy	1	<b>76.35</b>	
122	<b>R32128-37</b>	32128-37	Nut - 7-16-14 Hx Serr Fl	2	<b>3.25</b>	
123	<b>R325-17</b>	01-150-0640, 01-150-0850, 01-178-0832, 01-178-0836, 20-97-AGD, 325-17, 325-18, 48-9260	Bolt - Hex Head	1	<b>2.75</b>	
124	<b>R109-5009</b>	109-5009	Bushing - Suspension - Rubber	6	<b>2.95</b>	
125	<b>R116-0797-03</b>	116-0797-03	Link-Lift - Deck	1	<b>78.60</b>	
126	<b>R116-0780</b>	116-0780	Bolt - Hx HD Fl Shoulder	2	<b>8.45</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 74903  
52in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
127	<b>R453022</b>	01-166-0480, 01-166-1220, 21-3880, 217-21, 30-8550, 30-9110, 3256-28, 3256-44, 46-9030, Mar-71	Washer - 3/4 SAE	2	<b>0.43</b>	
128	<b>R32128-23</b>	32128-23, 3218-23, 99-5107	Nut - Lock Hex Flanged 1/2-13	6	<b>1.45</b>	
129	<b>R109-5010</b>	109-5010	Spacer	6	<b>3.65</b>	
130	<b>R112-4230-01</b>	112-4230-01	Plate- Skid	1	<b>49.10</b>	
131	<b>R3233-34</b>	3233-34	Carriage Bolt - 1/2-13 x 2 1/2 Grade 5	3	<b>7.15</b>	
132	<b>R116-0886</b>	116-0886	Spring - Extension	1	<b>86.85</b>	
133	<b>R254-78</b>	01-102-0060, 01-102-0130, 1-633585, 254-78, 32-7790, 32-9580, 93-4813	Tapered Bearing Cone	4	<b>6.05</b>	
134	<b>R254-72</b>	01-103-0050, 01-103-0120, 01-103-0140, 1-543508, 254-71, 254-72, 40439, 62-3340, 99-4511	Cup - Bearing	4	<b>3.85</b>	
135	<b>R115-7461-01</b>	115-7461-01	Baffle Assy	1	<b>107.95</b>	
136	<b>R116-0459-03</b>	116-0459-03	Lift - Rear Deck	1	<b>193.20</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

*Zero Turn Mower with 52in deck - Model 74903  
52in Side Discharge Deck*



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
137	<b>R114-5870</b>	114-5870	Idler Arm Assy with Bushings	1	<b>117.15</b>	
138	<b>R1-303514</b>	1-303514	Bearing - Flanged	2	<b>13.15</b>	
139	<b>R103-4882</b>	103-4882	Grease Cap - Castor	1	<b>4.20</b>	
140	<b>R109-9066</b>	109-9066	Yoke - Adjust - Deck	4	<b>4.80</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.