



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 74906  
Traction Unit



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 74906  
Traction Unit



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
<b>Belts</b>						
20	<b>R109-3388</b>	109-3388, 126-9835	Belt - V Hydro	1	<b>27.70</b>	
<b>Tires</b>						
40	<b>R115-3589</b>	115-3589	Tire & Wheel - 23x9.50-12 (4 Ply)	2	<b>234.35</b>	
40	<b>R127-9514</b>	127-9514	Tire & Wheel Assy - 23x9.50-12 Turf Master 4 Ply	2	<b>192.10</b>	
41	<b>RCT6L08381</b>	1-633993, 1-653160	Tire - 23x9.50-12 Nhs (4 Ply) Carlisle Turf Master	2	<b>110.95</b>	
42	<b>R232-27</b>	232-27, 232-31	Stem - Valve w/ Cap	2	<b>4.15</b>	
<b>Hoses</b>						
50	<b>R109-0302</b>	109-0302	Hose - Fuel	1	<b>5.40</b>	
<b>Gauges and Controls</b>						
61	<b>R343060</b>	218-412, 32-8380, 33-2010, 62-7770, 63-8360, 94-2618	Ignition - Key Set/2	1	<b>2.75</b>	
62	<b>R218-578</b>	218-578, 95-2438	Fuse - 10 Amp	1	<b>1.45</b>	
63	<b>R150812</b>	109102, 109355, 150812, 218-581	Fuse - 15 Amp	1	<b>2.45</b>	
64	<b>R116-1620</b>	116-1604, 116-1620	Clutch - Warner Pto Clutch	1	<b>306.70</b>	

## Other Parts Available

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 74906  
Traction Unit



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
70	<b>R233-42</b>	1-603175, 120-9752, 233-42, 233-47	Knob	1	<b>6.80</b>	
71	<b>R2412-98</b>	2412-98	Clamp - Spring - Hose 1/4	2	<b>0.57</b>	
72	<b>R400264</b>	01-150-0180, 01-178-0610, 20-48-AD, 20-48-AGD, 32-9160, 3224-3, 323-29, 323-7, 400264, 908035P	Bolt - Hex HD 3/8-16 x 1-1/4	4	<b>0.40</b>	
73	<b>R104-8301</b>	104-8301, 104-9301, 109-6658, 133-7570	Locknut - 3/8-16 Nylon Flanged	8	<b>0.84</b>	
74	<b>R116-1746</b>	116-1746	Wheel Hub Assy	2	<b>127.20</b>	
75	<b>R116-1696</b>	116-1696	Stud - Wheel	8	<b>2.45</b>	
76	<b>R126-1789</b>	126-1789	Fuel Cap - Ratcheting	1	<b>23.30</b>	
77	<b>R116-6317</b>	116-0133, 116-6317	Spring - Extension	1	<b>17.50</b>	
78	<b>R109-5668</b>	109-5668	Grip - Control Lever - Foam	2	<b>10.90</b>	
79	<b>R116-0039</b>	116-0039	Lever - Motion Control - RH	1	<b>32.95</b>	
80	<b>R116-0040</b>	116-0040	Lever - Motion Control - LH	1	<b>32.60</b>	
81	<b>R1-633268</b>	1-633268	Grip - Lever - Foam	1	<b>8.20</b>	
82	<b>R109-6589</b>	109-6589	RH Steering Handle Assy	1	<b>51.25</b>	
83	<b>R109-6590</b>	109-6590	LH Steering Handle Assy	1	<b>51.25</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Z Master Professional 5000 Parts

Zero Turn Mower with 52in deck - Model 74906  
Traction Unit



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Price Each	Order Quantity
84	<b>R453017</b>	01-166-0050, 01-166-0240, 01-166-0800, 24-13-AD, 24-14-AD, 32-8110, 3256-26, 3256-6, 453017, 69-8980, 87-7270	Washer - Flat 1/2	2	<b>0.28</b>	
85	<b>R46-6560</b>	46-6560	Bushing	2	<b>3.55</b>	
86	<b>R109-6919</b>	109-6919	Washer - Clutch	1	<b>3.55</b>	
87	<b>R1-603610</b>	1-603610	Washer-Spring	2	<b>2.60</b>	
88	<b>R109-9905</b>	109-9905	Sheave - 6 in Dia with 1.125 in Bore	1	<b>47.85</b>	
89	<b>R443818</b>	01-191-0813, 3218-18, 3218-5, 3248-18	Nut - 1/2-13 Hex Jam Zinc	2	<b>0.35</b>	
90	<b>R242-50</b>	242-50	Nut - 1/2-20 Wheel	8	<b>1.50</b>	
91	<b>R1-523420</b>	1-523420	Bumper - Rubber	2	<b>9.95</b>	
92	<b>R109-8107</b>	109-8107	Pump Linkage Rear Assembly	2	<b>53.05</b>	
93	<b>R1-633152</b>	1-633152	Balljoint - LH	2	<b>17.20</b>	
94	<b>R1-543017</b>	1-543017	Balljoint - RH	2	<b>17.20</b>	
95	<b>R1-323245</b>	1-323245	Spring - Compression	4	<b>4.20</b>	
96	<b>R3219-2</b>	01-188-0524, 22-12-BJKD, 3219-2, 915720	Nut - 5/16-24 Zinc	4	<b>0.37</b>	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.