


Replaces Toro Groundsmaster 4000-D Parts



Rotary Mower - Model 30605 Lift, Steer and Fan Hydraulic Assembly





Replaces Toro Groundsmaster 4000-D Parts



Rotary Mower - Model 30605 Lift, Steer and Fan Hydraulic Assembly

	R&R Part No.	OEM Part No.	Description	Qty Req	Price Order Each Quantity
Hose	s				
50	R127-3737	127-3737	Hydraulic Hose Assy	1	77.20
51	R127-3738	127-3738	Hydraulic Hose Assy	1	54.35
52	R127-3736	127-3736	Hydraulic Hose Assy	1	75.70
53	R100-3833	100-3833	Hydraulic Hose Assy	1	53.75
54	R121-1567	121-1567	Hydraulic Hose Assy	1	71.45
55	R121-1566	121-1566	Hydraulic Hose Assy	1	72.15
56	R106-3692	106-3692	Hydraulic Hose Assy	1	56.65
Othe	r Parts Available				
70	R59-7410	59-7410	Tip-Nipple	2	21.20
71	R340-127	340-127	Nut - Bulkhead	2	5.95
72	R340-71	340-71	Fitting - Straight	2	13.10
73	R340-70	340-70	Nut - Lock	2	2.45
74	R354-79	354-79	Cap-Dust	2	5.10
75	R3290-378	30-1740, 3290-378, 52-6570, 60-4340	Cable Tie	7	0.37